

DISTRIBUTION: ARCHITECT FIELD OWNER CONTRACTOR OFFICE
 MECH/ELEC ENG. FILE

FIELD REPORT

M. G. McLaren, P. C.
Consulting Engineers
100 Snake Hill Road
West Nyack, NY 10994

PROJECT: Contact Tank, Town of Greenburg FIELD REPORT NO: 01
ENGINEER'S PROJECT NO: 99010

Date: January 21, 2003 Weather: Sunny
Time: Temp. Range: 15°

Work in Progress: Present at Site:
Tony Capicotto, Dolph Rothfeld
Michael McGarvey, P.E. Town Eng. Greenberg
Phil Gonnella, Tnemec
Stephen Wells, Spectra (applicator for materials
inside tank)
W. Richard Mahoney, M. G. McLaren, P.C.

REPORT BY: W. Richard Mahoney, P.E.

OBSERVATIONS:

I made a field visit because there were reports that there were leaks in the tanks while they were testing the tank.

It was noted by Mike McGarvey that there was some movement of air and water through the tank on the top of the slab which would indicate that the coating inside the tank for the top slab was not a complete coating. There must have been some cracks in it. There was also an indication that water was moving between the construction joint between the wall and the top slab.

cc: 99010